


Material: H13

Hardness: Core = 40-45RC

Surface = 70-72RC

P	S	Product Code		
		L 6"	L 10"	L 14"
3/64	1/2	E0306 - 1/2	E0310 - 1/2	
1/16	1/2	E0406 - 1/2	E0410 - 1/2	
5/64	1/2	E0506 - 1/2	E0510 - 1/2	E0514 - 1/2
3/32	1/2	E0606 - 1/2	E0610 - 1/2	
7/64	1/2	E0706 - 1/2	E0710 - 1/2	E0714 - 1/2
3/64	1	E0306 - 1		
1/16	1	E0406 - 1		
5/64	1	E0506 - 1		

P	S	Product Code		
		L 6"	L 10"	L 14"
3/32	1	E0606 - 1		
7/64	1	E0706 - 1		
3/64	2	E0306 - 2	E0310 - 2	E0314 - 2
1/16	2	E0406 - 2	E0410 - 2	E0414 - 2
5/64	2	E0506 - 2	E0510 - 2	E0514 - 2
3/32	2	E0606 - 2	E0610 - 2	E0614 - 2
7/64	2	E0706 - 2	E0710 - 2	E0714 - 2



Material: H13

Hardness: Core = 40-45RC

Surface = 70-72RC

Product Code	P	S	L	Over Size
E0310 - 1/2OS	3/64	1/2	10"	+0.005
E0310 - 2OS	3/64	2	10"	+0.005
E0410 - 1/2OS	1/16	1/2	10"	+0.005
E0410 - 2OS	1/16	2	10"	+0.005
E0510 - 1/2OS	5/64	1/2	10"	+0.005
E0510 - 2OS	5/64	2	10"	+0.005
E0610 - 1/2OS	3/32	1/2	10"	+0.005
E0610 - 2OS	3/32	2	10"	+0.005
E0710 - 2OS	7/64	2	10"	+0.005